

**National Transportation Safety Board
Washington, DC 20594**

Brief of Incident

Adopted 12/30/2003

CHI03IA096				
File No. 14535	03/18/2003	Saginaw, MI	Aircraft Reg No. N1114N	Time (Local): 22:25 EST
Make/Model: Cessna / 208B			Fatal	Serious
Engine Make/Model: Pratt & Whitney / PT6A			Crew 0	Minor/None 1
Aircraft Damage: Minor			Pass 0	0
Number of Engines: 1				
Operating Certificate(s): None				
Name of Carrier: Mid Atlantic Freight, Inc.				
Type of Flight Operation: Non-scheduled; Domestic; Cargo				
Reg. Flight Conducted Under: Part 135: Air Taxi & Commuter				
Last Depart. Point: Traverse City, MI			Condition of Light: Night/Dark	
Destination: Same as Accident/Incident Location			Weather Info Src: Weather Observation Facility	
Airport Proximity: On Airstrip			Basic Weather: Visual Conditions	
Airport Name: MBS International			Lowest Ceiling: None	
Runway Identification: 5			Visibility: 10.00 SM	
Runway Length/Width (Ft): 8002 / 150			Wind Dir/Speed: 040 / 012 Kts	
Runway Surface: Asphalt			Temperature (°C): 0	
Runway Surface Condition: Dry			Obstr to Vision: None	
			Precipitation: None	
Pilot-in-Command			Flight Time (Hours)	
Age: 24				
Certificate(s)/Rating(s)			Total All Aircraft: 4821	
Commercial; Multi-engine Land; Single-engine Land; Single-engine Sea; Glider			Last 90 Days: Unk/Nr	
Instrument Ratings			Total Make/Model: 3330	
Airplane			Total Instrument Time: 816	

The pilot executed an emergency landing after reporting smoke in the cockpit. The aircraft sustained minor damage during the incident. The pilot was treated at a local hospital and released. Shortly before landing the pilot reported noticing smoke in the cockpit. He reported he opened a vent, which cleared the smoke, and subsequently landed without incident. After landing, however, the vent did not adequately clear the smoke. He taxied to the ramp and emergency personnel assisted him from the aircraft. Rescue personnel reportedly examined the aircraft for the source of the smoke. Although they noted an occasional odor, it was not strong enough to indicate a definite origin. There was no evidence of a fire. A post-incident review determined the engine bleed air pressure regulator had failed, allowing unregulated bleed air into the deice system. The temperature of the unregulated P3 air may be as high as 607 degrees Fahrenheit. The bleed air is routed through a supply line which runs through the left side door post. The line is constructed of thin-walled aluminum tubing and is wrapped in anti-chaffing tape. The source of the smoke was the tape which became overheated due to the unregulated bleed air. The pressure regulator and pneumatic supply line were replaced. The aircraft was subsequently returned to service and, after monitoring several flights, the problem did not recur.

Brief of Incident (Continued)

CHI03IA096
File No. 14535 03/18/2003 Saginaw, MI Aircraft Reg No. N1114N Time (Local): 22:25 EST

Occurrence #1: AIRFRAME/COMPONENT/SYSTEM FAILURE/MALFUNCTION
Phase of Operation: CRUISE

Findings

1. (C) BLEED AIR SYSTEM,GOVERNOR - FAILURE,TOTAL
2. (F) BLEED AIR SYSTEM,LINES - OVERTEMPERATURE

Findings Legend: (C) = Cause, (F) = Factor

The National Transportation Safety Board determines the probable cause(s) of this incident as follows.
Failure of the engine bleed air pressure regulator. A contributing factor was the anti-chaffing tape on the air supply line.